

LIP-3ECTC, LIP-1ECTC, LIP-33ECTC

CEA-709/IP Router

Installation instructions

Instructions de montage


Istruzioni di montaggio


Montageanweisung

Instrucciones de montaje


Montagevoorschrift

Monteringsanvisning






Connectors		
POWER	1	Power supply input GND
	2	Power supply input PLUS
Connectors LIP-3ECTC		
TP/FT-10	3	not connected (NC)
CEA-709	4	Input B
	5	Input A
Connectors LIP-1ECTC		
TP/XF-1250	3	not connected (NC)
CEA-709	4	Input B
	5	Input A
Connectors LIP-33ECTC		
TP/FT-10	3	not connected (NC)
CEA-709	4	Input B
	5	Input A
TP/FT-10	6	not connected (NC)
	7	Input B
CEA-709	8	Input A



4.5 lb-in/0.5 Nm


Weidmüller
BLZP 5.08

0.2 - 2.5 mm²



2 poles: Weidmüller BLZP 5.08/02/180

3 poles: Weidmüller BLZP 5.08/03/180



Status LEDs

FT, TP-1250	GREEN flashing fast GREEN flashing 1 Hz RED permanent RED flashing fast	Traffic on CEA-709 port Not commissioned CEA-709 port damaged CEA-709 traffic overload
----------------	--	---

Please update the firmware of the device first,
see www.loytec.com

User: admin
Password: loytec4u

35 mm x 7.5 mm DIN rail (EN 50022, BS 5584, DIN 46277-3)

