

WINMAG replacement dongle (USB instead of parallel)

Phone: +49 2131 40615 600

Faximile: +49 2131 40615 606



Part-No. WINMAG remplacé par un dongle USB 013645

Upgrade of basic software WINMAGplus. As a consequence of hardware exchange, the parallel dongle needs to be replaced by a USB dongle.

This license may be ordered separately (subsequently) only in conjunction with the auxiliary Part No. 013609. The update number of the basic license must be included when ordering. The license is used for connection of the Honeywell intrusion detection systems MB/HB, 5008. Please use order form on www.esser-systems.com.

Subject to change without notice!

Honeywell international Inc.